				COFORMA 'B'	
	Name of Consultant:-			OC Tech Structural Consultant	
1				"P M SHREE KENDRIYA VIDYALAY"	
	Address			Situated at Mumbai Metro Line-6 Project, NCF Colony, Kanjurmarg, Bhandup West, Mumba	
				Maharashtra-400078.	
2	CTS	No./Ward/	UID		
3		No. of Storey		- Ground Floor + One Floor.	
4	Year of Construction		tion	1993. Aprox.30 Years Completed	
5		User Department			
6		Date of inspection by consultant		School Building	
7	Date of preparation of report		on by consultant	28 12 2024	
8	Vali	Validity period of report		28-12-2024 6 months from date of audit.	
9				o months from date of addit.	
	Mode of construction of existing bldg-			Nutherselod	
	i)			Not Inspected. RCC slab.	
		ii) Floors		230mm thk. Brick Masonary wall externally.	
	iii)			RCC beam of varying size.	
	iv)			RCC Column of varying size.	
		v) Columns		RCC Slab with waterproofing.	
10	vi)	Roof	dana antino	Description of Repairs	Year when work
10	History of Repairs done year-wise-		's done year-wise-	Description of http://	done
	Structural Repairs		ctural Repairs	-	-
	Tenantable Repairs				_
	Roof/Waterproofing			-	-
	Plumbing			<u> </u>	-
	Additional/Alterations if any			_	-
11	Condition of -				
	Cond	i) Internal plaster		Peeling off paint and marks of dampness observed at few locations.	
		ii)	External plaster	Cracks and bulges were observed at	multiple locations.
		iii)	Plumbing	Storm water drain and sewage do	wn take pipes at
		,	0	certain locations were found to be	e leaked and
ļ				damaged	
		iv)	Drains lines/chambers	Drainage lines leakages & damaged	condition at certain
				places	
12	Observations-				
	a)	Doors & windows don't close		Doors & windows closing properly.	
1	b)	L: DCC		Reinforcement steel exposed & corroded in slab, beam &	
	ć	Members		column at certain location.	
	c)) Settlement uneven flooring gaps		Settlement uneven flooring gaps were observed in	
		between skirting & floor		flooring at few locations.	
	d)			Foundation settlement was not present.	
	e)	Deflections/sagging		No Significant observation	
	f)	Major cracks in RCC Members		Major cracks observed Column & beam at certain locations.	
	al	g) Seepages/Leakagesh) Staircase area condition		Observed through toilet sunken slab in the few	
	51			locations	
	1.)			No Significant observation	
		Lift walls		Not present	
				-	alor
	\hat{p}	U.G. Tank		1	UF

85

1

- HARVEN HARS A

ONKAR ASHOK CHAVAN STRUCTURAL ENGINEER STATE OF MAHARASHTRA STATE/R/2022/APL/02813

प्राचार्य / Principal पीएम श्री केंद्रीय विद्यालय PM SHRI Kendriya Vidyalaya मांडुप, मुंबई /- Bhandup, Mumba

l : e

Э.

52