
Received Thro










एक कदम स्वच्छता की और



कार्यपालक अभियंता का कार्यालय

OFFICE OF THE EXECUTIVE ENGINEER

आइजोल केन्द्रीय मंडल, सी.पी.डब्लू.डी., जोमुआन विला, प्रथम तल, चौलमुन, आइजोल-796009(मिजोरम) AIZAWL CENTRAL DIVISION, CPWD, ZOMUAN VILLA, 1ST FLOOR, CHAWLHHMUN, AIZAWL-796009 (MIZORAM) Tel. No.0389-2330845, E-MAIL/ई-मेलः @cazcd@gmail.com./nez2eeazcd.cpwd@nic.in

No. 54(22)/ACD/2023-24/03

Dated:0//02/2024

To.

The Principal, Kendriya Vidyalaya, Project Pushpak, Zemabawk, Aizawl (Mizoram) – 796017.

"Structural Safety & Stability Certificate of Vidyalaya Building, Staff Subject:-

Quarters and Boundary Wall"-reg.

Reference:- Letter No. F.1856/400/2023/KV Aiz/102 Dated: 18/01/2024.

Sir.

In reference of the above, the permanent School Building, Staff Quarters and Boundary Wall of Kendriya Vidyalaya, Project Pushpak, Zemabawk, Aizawl, Mizoram-796017, has been inspected by the undersigned along with the concerned Assistant Engineer and it is certified that the Permanent School Building and Staff Quarters are apparently seems to be safe, but some parts of boundary wall do not seem safe due to the regular earth erosion from outer side of wall by heavy rain during the rainy season. Also, it is observed that erosion already started near Plinth at one location. So, it is suggested to renovate the boundary wall as well as protection against soil erosion at the earliest. considering structural safety and stability point of view.

> **Executive** Engineer, Aizawl Central Division, CPWD, Aizawl.

selfice and building in