



भारतसरकार/Government of India  
 केंद्रीयलोकनिर्माणविभाग/Central Public Works Department  
 चेन्नैकेंद्रीय- I मंडल /Chennai 1 Division  
 शास्त्रीभवन/Shastri Bhavan, 26, Haddows Road,  
 नुंगमबाक्कमचेन्नै/Nungambakkam, /Chennai - 600 006  
 e-mail: chneeccd1.cpwd@gov.in



☎ 044 - 28272621

Fax: 044-28220057

No:24(21)/C1D/2024-25/ 4250-53(H)

Dated: 03.10.2024

To

The Principal,  
 PM SHRI Kendriya Vidyalaya,  
 Gill Nagar,  
 Chennai - 600 094.  
 Email Id: [kvgngill@gmail.com](mailto:kvgngill@gmail.com)

**Sub: Structural stability of KV, Gillnagar – Reg****Ref:** Your letter No: 17111/2024-25 dated 20.09.2024

Kindly refer to the above cited subject and referred letter addressed to Chief Engineer, CPWD.

1. The Kendriya Vidyalaya, Gillnagar was inspected by the undersigned on 01.10.2024 along with the Assistant Engineer and the Officials of the school management in respect of structural stability.
2. The building is basically a combination of two parts joining an old and new structure. It is a very common that the cracks will develop upon joining of 2 structures constructed at different times but they are not structural cracks.
3. These cracks are mostly appeared at the corners and some are at beam level also.
4. Spalling of concrete appeared at some slab portions and some are already attended.
5. The toilets are maintained neat and clean and no prominent leakages are found.
6. Dampness observed in some walls that may be due to seepage of water through cracks.
7. Internal painting to be taken up.
8. Anti termite treatment to be taken up in some of the cupboards.

**It is certified that the structure is structurally safe** and it is advised to take up the above works for better maintenance and longevity of the building.

  
 G. Subrahmanyeswara Rao,  
 Executive Engineer,  
 C1D, CPWD, Chennai.

**Copy to**

1. The Chief Engineer, Chennai, CPWD, Chennai, for kind information.
2. The Assistant Engineer-1, C1D, CPWD, Chennai, for information.

  
 Executive Engineer