

Tele: 6860

Garrison Engineer Panagarh
Military Engineer Service
PIN 900 349
c/o 99 APO

2000/KVP/165/E2 dt 17 Sep 2025

K V Panagarh

FWD OF STRUCTURAL STABILITY CERTIFICATE FOR KV SCHOOL

1. Ref PM Shri KV Sangathan Panagarh letter No 25029/KVP/School Building/2025-26/509-510 Dated 10 Jun 2025.

2. It is intimated that the structural stability of KV School building is healthy and no major repair/renovation works are required. But the following observations have been raised by MES rep which are as under:-

2.1 Ground floor toilet (Boys) :- Heavy exposure of reinforcement in beams and slabs observed. Excessive damage of beams and roofs including heavy spelling found. Outside columns are found cracked due to corrosion of reinforcement. After repair this portion of building may be used of as store for limited use and not as toilet for safely. It should be considered new toilet block in future.

2.2 Roof slab :- Existing APP laid over roof slab, found completely damaged causing seepage of water inside the class rooms. Need fixing of new APP membrane sheet after padding of roof concrete with finishing.

2.3 Back side of building :- Chajjas (sunshades) are found heavily damaged at location. Longitudinal corrosion crack along with spelling of concrete observed at locations in ground floor back side outer columns.

3. It is intimated that special repair of KV School bldg wk has been sanctioned & Scope of wk was given to this office recently and DCS is under prep for tender action.

4. This is for your info and further necessary action please.


(SR Rajput, IDSE)
EE
Garrison Engineer

Encls: As above

Copy to:-

HQ 417 Engr Bde

70 Engineer Regiment

} for info and further necessary action please