



**EDUCATION DEPARTMENT
GOVERNMENT OF SIKKIM
GANGTOK**

Memo No.- 145/AE/Gtk/Edu/Gor

Date- 04/04/26

BUILDING SAFETY CERTIFICATE

This is to certify that a physical inspection of "**Kendriya Vidyalaya Gangtok**" having **C.B.S.E. Affiliation No. 1800001** and **School No. 39584** located at Tadong, Gangtok in **East Sikkim** was conducted on 2nd of April, 2026 by the field engineer of Education Department (Gangtok), where it was found that the above-mentioned School comprises of 2 numbers of R.C.C framed structure and 1 GCI Sheet Temporary Structure with the following details as mentioned below: -

- **Admin Block** - One 1 storeyed RCC building. It comprises of: -
 - a) Principal's Chamber
 - b) Examination Department
 - c) Music Room
 - d) Accounts Room
 - e) 2 Washrooms
 - f) 1 Classroom
 - g) Office RoomThe total plinth area is 2139.00 Sq. ft.
- **Academic Block** - One 2 storeyed RCC building. It comprises of: -
 - a) 13 Classrooms
 - b) Computer Lab
 - c) 2 WashroomsThe total plinth area is 4800.00 Sq. ft.
- **GCI Sheet Structures** - One storeyed Structure. It comprises of: -
 - a) 1 Classroom
 - b) 1 Biology Lab
 - c) 1 Physics Lab
 - d) 1 Library
 - e) 1 StaffroomThe total plinth area is 1305.00 Sq. ft.

The visual inspection revealed that the columns, beams and slab of Academic Block does not have cracks or shear stress of any kind, the partitions were also found to be free from cracks, till date, the school building does not have any significant damages and defects, hence, the structure of the Academic block can be certified to be fairly safe.

NOTE: However, Admin Block Needs to be Repaired Immediately.

Note: It is recommended that the emergency exits should be made available as directed during the site visit for safe evacuation in the case of emergencies.

This certificate is valid for a period of one year from the date of issue.

**Junior Engineer (Gtg),
Education Department,
Govt. of Sikkim.**

**Assistant Engineer (Gtg),
Education Department,
Govt. of Sikkim.**