भारत सरकार
कार्यपालक अभियन्ता- सम्बलपुर का कार्यालय
केंद्रीय लोक निर्माण विभाग
प्लॉटनं. 1399 से 1403, कैन्सिर रोड
अँइठापल्ली, सम्बलपुर, ओडिशा पिन-768004
ई-मेल: sbpeecspd@cpwd.gov.in
ई-मेल: spdcpwd@gmail.com

Government of India
O/o The Executive Engineer - Sambalpur
Central Public Works Department
Plot No. 1399 to 1403, Kainsir Road
Ainthapalli, Sambalpur, Odisha, Pin-768 004
e-mail: sbpeecspd@cpwd.gov.in
e-mail: spdcpwd@gmail.com

क्र.23(17)/स.म/के.लो.नि.वि/2026-27/570 (हि)

दिनांक: २१ .09.2026

स्पीडपोस्ट/ ई-मेल/बाईहैंड

सेवा में,

The Principal
PM SHRI KENDRIYA VIDYALAYA NO.2
Behind New Palace, Shastri Nagar
Balangir- 767001 (O)
(E-Mail: principalkv2bgr@gmail.com)

विषय: Issuance of Building Safety Certificate -reg.

संदर्भ पत्र संख्या : F. No. 150346-2/2026-27/KV No2 BGR/1156/90 Dated 18.08.2026

महोदय,

With reference to your letter above, The school building has been inspected visually by the concerned Assistant Engineer-II & undersigned. With reference to its present condition, it seems that the school building requires annual repair and maintenance work periodically so as to assure prevent the building from persistent water seepage and consequent deterioration of structural members. Besides all, the building is presently structurally safe in all-round to conduct classes and run the session.

Hereby, the Building Safety Certificate is issued based on the visual inspection carried out and the condition of the accessible structural components observed at the time of inspection, no apparent major structural distress or visible deficiency affecting the general structural stability of the building has been noticed.

Accordingly, the existing school building is considered structurally safe for its intended use as a school building, subject to the following conditions:

1. The building shall continue to be used only for its intended purpose and sanctioned occupancy.
2. No unauthorized structural alteration, addition, removal of structural members, cutting/chasing of RCC beams, columns or slabs, or other modification affecting the structural system shall be carried out without prior approval of the competent authority.
3. The building shall be maintained properly and all defects noticed during routine maintenance, including leakage/seepage, corrosion of reinforcement, cracks in structural members, settlement, dampness or other signs of deterioration, shall be attended to promptly.
4. The roof, rainwater drainage system, plumbing and sanitary installations shall be maintained properly so as to prevent persistent water seepage and consequent deterioration of structural members.
5. Any future proposal for additional floor, heavy equipment, change of occupancy/use, installation of heavy loads or structural modification shall be referred to the competent technical authority for examination and approval before execution.

6. The school authorities shall immediately intimate CPWD if any new major structural crack, excessive deflection, settlement, tilting, corrosion of reinforcement, spalling of concrete or any other unusual structural distress is noticed in the building.

7. This certificate is based on the visual inspection of accessible portions of the existing building and available records/information. It does not constitute a detailed structural audit, non-destructive testing or re-analysis of the original structure unless specifically carried out separately.

8. The certificate shall remain subject to periodic inspection and proper maintenance of the building and shall not be construed as a waiver of the requirement for carrying out any detailed structural investigation or testing if considered necessary by the competent authority.

In view of the above, the existing school building of **PM Shri Kendriya Vidyalaya No.2, Balangir, constructed by CPWD in the year 2005**, is certified to be **structurally safe for its present intended use as a school building**, based on the visual inspection carried out; subject to the conditions mentioned above.

This certificate is issued on the request of the Principal, PM Shri Kendriya Vidyalaya No. 2, Balangir, Odisha; for official record and further necessary action.

धन्यवाद

भवदीय

21/9/26

श्रवण कुमार
कार्यपालक अभियन्ता- सम्बलपुर
के.लो.नि.वि, सम्बलपुर

.प्रतिलिपि:

1. Office File.

कार्यपालक अभियन्ता- सम्बलपुर