



DIRECTORATE OF NEW AND RENEWABLE ENERGY, HARYANA
HAREDA/ Akshay Urja Bhawan, Sector-17, Panchkula
Phone 0172-2585733, EPBX No.2587233, 2587833, E-mail-hareda@chd.nic

From

The Director General,
New & Renewable Energy Department & HAREDA, Haryana,
AkshayUrjaBhawan, Institutional Plot No.-1, Sector-17,
Panchkula.

To

The Additional Deputy Commissioner
-cum-Chief Project Officer, NRE,
Jhajjar..

Memo no. HAREDA/2022/Pump/6699


Dated: 31-08-22

Subject: Clarification regarding repair of defects occurred in installed Solar Pump.reg.

In reference to your letter no. 569 dated 29.7.2022 vide which you were requested to sought clarifications on repairing of pumps. In this regard it is hereby clarified that:-

1. Damaged caused to surface pump due to entering of water in it is not covered under warranty as surface pumps are not designed to be submerged in the water and IP (65) is not sought in case of surface pumps in EESL/06/2020-21/KUSUM/SWPS/1-10 HP/Off Grid/202101032 tender. So, the farmers are advised to protect surface pumps from water.
2. The firms are directed to repair/replace the submersible pumps if same is defected due to wear and tear caused by excessive sand in water as defects caused due to wear and tear also covered under warranty as per terms and conditions of EESL/06/2020-21/KUSUM/SWPS/1-10 HP/Off Grid/202101032 tender. The firms are also advised to ensure the quality of borewell before installation of solar pumps so that farmers can be directed to carry out proper cavity of borewell.

This is for your information and further necessary action please.


(Sombir Singh)
Scientific Engineer 'A',
for Director General, NRE&HAREDA
Haryana, Panchkula.

Cc:-

1. All the ADC-cum-CPO's of State for their information please.
2. All the Empanelled firms (list attached) for information and strict compliance of directions.