

ಭಾರತ ಸರ್ಕಾರ Brod, derbersiolech auten ಕಾರ್ಯನಿರ್ವಾಹಕ ಎಂಜಿನಿಯರ್ -II (cloristed), A. &. dug. B 12 ನೀ ಮಹಡಿ, ಸರ ವಿಶ್ವೇಶ್ವರಿಯ್ಯ ಶೇಂದ್ರೀಯ ಭವನ, ದೇವ್ಯಾಬಾರು, ಫೈಓವರ್ ಹತಿರ, ದೂಮ್ಮೆಬೂರು

Stortwood - MED OLO

भारत सरकार केन्द्रीय लोक निर्माण विभाग कार्यपालक अभियंता-॥ (बेंगतर), के लो.नि.वि. 12 वी मंजिल, सर विस्वरवरिया के द्रीय भवन डोम्लूर फ्लाईओवर के पास होम्स्र, बैंगल्स - ५६० ०७१

GOVERNMENT OF INDIA CENTRAL PUBLIC WORKS DEPARTMENT Executive Engineer-II (Bengaluru), CPWD, 12TH Floor Visvesvaraya Kendriya Bhawan, Near Domlur Flyover DOMLUR, BANGALORE-71 Phone: 080-25359444



सं.24(4)/ EE-II/CPWD/2024-25/145/3 (हि.)

दिनांक: 21 /11/2024

To/सेवामें,

The Principal, PM Shri Kendriya Vidyalaya, ASC Centre♥S), Bengaluru, Bangalore - 560047

विषय: - Structural Safety Certificate for Pm SHRI KV ASC Centre(S) Bangalore-reg.

संदर्भ :- Your letter No.KV ASC/BGR/2024-218 dated 16.11.2024

\*\*\*\*\*

महोदय,

With reference to the above, the undersigned along with Shri. Shri C Shashi Kalyan, AEE, BCSD 4/II CPWD, Domlur, Bangalore inspected your school on 16/11/2024. And noticed seepage in middle block of school and some cracks on the boundary wall. The school building of PM Shri Kendriya Vidyalaya at ASC Centre is found to be structurally safe and safe habitation from usual inspection.

However detailed structural investigation (or) audit is required to establish structural stability of the buildings.

भवदीया/ Yours Faithfully,

कार्यपालक अभियंता-II/Executive Engineer -II

कें.लो.नि.वि बैंगलोर-71/ CPWD, Bangalore-71

कन्द्रीय विप्रसितिपिः ndriya Vidyalaya

mend / Principal

क-दीय विप्रसितिपः- ASC Centre (5) अप.एस.सी. संदर्भिः The Assar Executive Engineer, BCSD 4/II, CPWD, Bangalore for inge-wififormation.

कार्यपालक अभियंता-II/Executive Engineer -II