



DIRECTORATE OF NEW AND RENEWABLE ENERGY, HARYANA

HAREDA/ Akshay Urja Bhawan, Sector-17, Panchkula

Phone 0172-2585733, EPBX No.2587233, 2587833, E-mail-hareda@chd.nic



From

The Director General,
New & Renewable Energy Department & HAREDA, Haryana,
AkshayUrjaBhawan, Institutional Plot No.-1, Sector-17,
Panchkula.

To

The Additional Deputy Commissioner
-cum-Chief Project Officer, NRE,
of all the Districts.

Memo no. HAREDA/2022/Pump/7892-7913 Dated: 19-9-22

Subject: Clarification regarding repair of defects occurred in installed Solar Pump.reg.

In continuation to this office letter no. 6694 dated 31.8.2022 vide which clarifications on repair of pumps was circulated. But now it has been observed that few firms are interpreting the clarification point no.1 which was relating to repair of surface pumps, firms are denying to repair surface pumps by taking plea that pump has failed due to the entering of water in it and same cannot be repaired as per said issued instructions. In this regard, it is clarified that any wear and tear arising out in surface pump is covered under warranty. Accordingly, the firm has to repair the same. Further the surface pump which gets defected only due to the submergence in water after due confirmation by District PO/APO is not covered under warranty.

This is for your information and further necessary action please.

(Sombir Singh)
Scientific Engineer 'A',
for Director General, NRE&HAREDA
Haryana, Panchkula.

Cc:-

All the Empanelled firms (list attached) for information and strict compliance of directions.