

WITH SEAL

STRUCTURAL SAFETY CERTIFICATE

NAME OF WORK: Structural repair of distressed RCC members, plaster repair, external and internal painting and replacement of damaged portion of water proofing treatment of terrace at Kendriya Vidyalaya, Koliwada, Antop Hill, Mumbai-37.

DATE OF COMPLETION: 13.10.2022

NAME OF CONSTRUCTION AGENCY: CPWD

Certified that the structural repairs / maintenance related work of at Kendriya Vidyalaya, Antop Hill, Sector-I has been carried out with proper earth quake provisions as per the structural audit approved by IIT, Mumbai and the building, which has been constructed, is STRUCTURALLY SAFE.

कार्यपालक अभियंता (सि)

मुंबई IV (SIGNATURE)

HEAD OF THE DEPARTMENT

WITH SEAL