Name of the unit		M/s. Total Polyworld (Unit-II)			
Address		Sr. no. 142/4, Part-A, Village Dabhel, Daman.			
Area		Dabhel			
Category		Category - II			
Applied for		Consent to Operate			
Consent granted for		Consent to Establish for "Plastic reprocess granules (from 1 <sup>st</sup> generation inhouse waste) - 7200 MT/Year and Rolls, sheets, films, plastic strapping patti, sutli and all kind of plastic packaging materials – 3600 MT/Year"			
Sr. No.		Documents required		Submitted	
1.	Application	n in Form XIII under Water Act. Yes (C/225)			
2.	Application	n in Form I under Air Act.	Yes (C/221)		
3.	Declaration	eclaration letter showing capital investment.		Yes (C/187)	
4.	under Wat	ent fees demand draft of Rs. 16,000/- and Rs. 6000/- Yes (C/223 & C/161)  Water Act and Air Act. (from which Rs. 4000/- ns as deposit)			
5.	Display Sig	play Sign Board.		Yes (C/215)	
6.		for authorization to handle by data sheet in Form – I.	Yes (C/213)		
7.		ata Sheet Format		Yes (C/209)	
8.	Copy of ha	azardous waste manifest in Form 13.		N.A.	
9.	Copy of me	membership of common TSDF.		N.A.	
10.	Copy of an	alysis of treated effluent.		N.A.	
11.	Copy of st monitoring	tack monitoring report and ambient air quality N.A. report.			
		Effluent discharge with	h quantity		
		Consumption	Discharge	Discharge	
Domestic water		500 Lit./Day	500 Lit./Day	500 Lit./Day	
Industrial water					
		Air Emission	1		
Installation		Fuel used	Stack/Acoust	Stack/Acoustic	
N.A.		N.A.	N.A.		
		Details of Effluent Treatmen	at Plant/APCDS		
ETP N.A.					
APCDS		N.A.			
		Monitoring Repo	orts		
		Effluent Norm	IS		
		Norms as per consent	As per report	As per report	
pH		6.5-9.0			
Suspended Solids		Not to exceed 100 mg/Lit			
BOD		Not to exceed 100 mg/Lit			
ÇOD		Not to exceed 250 mg/Lit			
Oil & grease		Not to exceed 10 mg/Lit			

## Observations and Recommendations:

The unit was inspected on 13/06/2017 and at the time of inspection following observations were noted:

- > The unit was in operation at the time of inspection.
- > The unit has installed Display signboard at the main gate.
- > Raw material used in manufacturing process was Plastic granules (PP/LDPE), master batch, and Plastic scrape material.
- > Products being manufactured at the time of inspection were Plastic tubings, sheets/films, bags, and plastic reprocessed granules.
- > Manufacturing process involved at the unit was Mixing- Extrusion Cutting/Sealing -Pelletizing of granules - Packing.
- ➤ Machineries installed within the premises of the unit were Blow film extrusion 5 no, Cutting/Sealing m/c - 03 no, Compressor - 01 no, Cooling tower - 01 no, Aglo/mixer m/c -03 no, Extruder (re-process granular) m/c -03 no.
- > Plastic scrape materials were stored at separate area and reuse within the premises.
- > The unit was availed with soak pit tank for disposal of domestic wastewater.

In view of above, Consent to Operate (Category-II) for manufacturing of "Plastic reprocess granules (from 1st generation inhouse waste) - 7200 MT/Year and Rolls, sheets, films, plastic strapping patti, sutli and all kind of plastic packaging materials - 3600 MT/Year" under water act and air act for the period upto 31/05/2020 may be issue.

Submitted for your kind perusal and approval, Sir.

Member Secretary