For the Performance Grant of 2018-19					
S. No.	Indicators	MoHUA Benchmark	Service Level 1 Flux service Status 2017-18	Sencimalis Target 2018-19	
Wat	er Supply Services			00	
1	Coverage of water supply connections	100%	85	90 135	
2	Per capita supply of water	135 lpcd	100	50	
3	Extent of metering of water connections	100%	0	15	
4	Extent of Non-Revenue Water (NRW)	20%	15	5	
5	Continuity of water supply	24 hours	4	100	
6	Quality of water supplied	100%	98	70	
7	Efficiency in redressal of customer complaints	80%	75	100	
8	Cost recovery in water supply services	100%	85	90	
9	Efficiency in collection of water supply related charges	90%	75		
Sew	age management (Sewerage and Sanitation)		0	0	
1	Coverage of toilets	100%	0	0	
2	Coverage of sewage network services	100%	0	0	
3	Collection efficiency of the sewage network	100%	0	0	
4	Adequacy of sewage treatment capacity	100%	0	0	
5	Quality of sewage treatment	100%	0	0	
6	Extent of reuse and recycling of sewage	20%	0	0 .	
7	Efficiency in redressal of customer complaints	80%	0	0	
8	Extent of cost recovery in sewage management	100%	0	0	
9	Efficiency in collection of sewerage charges	90%	-		
Soli	d Waste Management				
1	Household level coverage of Solid Waste Management services	100%	65	100	
2	Efficiency of collection of municipal solid waste	100%	40	100	
3	Extent of segregation of municipal solid waste	100%	45	100	
4	Extent of municipal solid waste recovered	80%	0	40	
5	Extent of scientific disposal of municipal solid waste	100%	0	50	
6	Efficiency in redressal of customer complaints	80%	65 45	80 55	
7	Extent of cost recovery in SWM services	100%		80	
8	Efficiency in collection of SWM charges	90%	60	80	
	n Water Drainage	1000/	+		
1	Coverage of Storm water drainage network	100%	0	0	
		0%	0	0	
For the Performance Grant of 2018-19, SEB Status 0(2017-16)					
	Coverage of Water Supply (24 X 7) in all Public/Community Toilets	24X7		NO	
2	Percentage of waste being processed scientifically*	100%	0		

अधिशासी अधिकारी नगर पालिका परिषद दुगङ्डा (पेड़ी मदवाल)