	Service Level Benchmarks							
S. No.	Indicators	Moud Benchmark	For the Performance Grant of 2017-18		For the Performance Grant of 2018-19		For the Performance Grant of 2019-20	
Wate	er Supply Services		Status 2016-17	Target 2017-18	Status 2017-18	Target 2018-19	Status 2018-19	Target
1	Coverage of		2016-17	2017-18	2017-18	2018-19	2010-19	2019-20
2	Coverage of water supply connections	100%	80%	90%				
3	r et capita supply of water	135 lpcd	110	135				
4	Extent of metering of water connections	100%	0	0				
5	Extent of Non-Revenue Water (NRM)	20%	20	20				
6	Continuity of water supply	24 hours	8	18				
	Quality of water supplied	100%	80	100				
7	Efficiency in redressal of customer complaints	80%	80	100				
8	cost recovery in water supply services	100%	75	100				
9	Efficiency in collection of water supply related	100%	/3	100				
_	cnarges	90%	80	80				
Sew	age management (Sewerage and Sanitation)							
1	Coverage of toilets	100%	0	0				
2	Coverage of sewage network services	100%	0	0				
3	Collection efficiency of sewage network	100%	0	0				
4	Adequacy of sewage treatment capacity	100%	0	0				
5	Quality of sewage treatment	100%	0	0				
6	Extent of reuse and recycling of sewage	20%	0	0				
7	Efficiency in redressal of customer complaints	80%	0	0				
8	Extent of cost recovery in sewage management	100%	0	0				
9	Efficiency in collection of sewerage charges	90%	0	0				
Solid	Waste Management							
1	Household level coverage of Solid Waste Management services	100%	80	90				
2	Efficiency of collection of municipal solid waste	100%	80	90				
3	Extent of segregation of municipal solid waste	100%	80	90				
4	Extent of municipal solid waste recovered	80%	70	80				
5	Extent of scientific disposal of municipal solid waste	100%	50	90				
6	Efficiency in redressal of customer complaints	80%	80	80				
7	Extent of cost recovery in SWM services	100%	10	80				
8	Efficiency in collection of SWM charges	90%	85	90				T
	n Water Drainage							1
	Coverage of Storm water drainage network	100%	0	0		†	†	†
1	Incidence of water logging / flooding	0%	0	0	-	t	<u> </u>	
2			For the Performance Grant of 2017-18 : SLB Status of 2016-17		For the Performance Grant of 2018-19 : SLB Status of 2017-18		For the Performance Grant of 2019-20 : SLB Status of 2018-19	
1	Coverage of Water Supply (24 X 7) in all Public/Community Toilets	24 hours	Yes		NΘ		. 70	
	Percentage of waste being processed scientifically	%	80					

Note: Please see the following link for instructions to provide the status of Service Level Benchmarks current year/target year

Format_14FC_PG_2017-18_DOIWALA NPP.xlsx

(विजय पीर्एस० चौहान) अधिशासी अधिकारी नगर पालिका परिवद ओईवाला

20-08-18