-	For the Performance Gra	nt of 2018-19			
S	Indicators	MoHUA Benchmark	Service Level Benchmarks		
10/6	to Complete		Status 2017-18 —	Target 2018-19	
	cater Supply Services				
2	and the supply conflections	100% .	90	100	
3		135 lpcd	114	125	
- 4	- Water Connections	100%	5	50	
_ - -5	- The state of the state (NKVV)	20%	15	15	
6	The state of traces supply	24 hours	6	10	
7	The supplied	100%	100	100	
8	The state of the s	80%	80	100	
<u>9</u>	The street of the water supply services	100%	90	100	
	The supply related charges	¹ 90%	90	100	
1	vage management (Sewerage and Sanitation)				
2	Coverage of toilets	100%	70	85	
3	Coverage of sewage network services	100%	70	80	
4	Collection efficiency of the sewage network	100%	100	100	
5	Adequacy of sewage treatment capacity	100%	50	80	
6	Quality of sewage treatment	100%	85	90	
_	Extent of reuse and recycling of sewage	20%	20	20	
7	Efficiency in redressal of customer complaints	80%	100	100	
8	Extent of cost recovery in sewage management	100%	30	50	
9	Efficiency in collection of sewerage charges	90%	80	100	
oli	d Waste Management				
1	Household level coverage of Solid Waste Management services	100%	90	100	
2	Efficiency of collection of municipal solid waste	100%	90	95	
3	Extent of segregation of municipal solid waste	100%	30	50	
4	Extent of municipal solid waste recovered	80%	30	50	
5	Extent of scientific disposal of municipal solid waste	100%	0	25	
6	Efficiency in redressal of customer complaints	80%	90	100	
7	Extent of cost recovery in SWM services	100%	0	40	
8	Efficiency in collection of SWM charges	90%	0	75	
	m Water Drainage		i i i i i i i i i i i i i i i i i i i	7,9	
1	Coverage of Storm water drainage network	100%	100	100	
	Incidence of water logging / flooding	0%	0	0	
2	For the Performance Grant of 2018-19:		The state of the s	V	
1	Coverage of Water Supply (24 X 7) in all Public/Community Toilets	24X7	YES		
2	Percentage of waste being processed scientifically*	100%	0		

