

For the Performance Grant of 2019-20

S. No.	Indicators	MoHUA Benchmark	Service Level Benchmarks	
			Status 2018-19	Target 2019-20
Water Supply Services				
1	Coverage of water supply connections	100%	90	100
2	Per capita supply of water	135 lpcd	135	100
3	Extent of metering of water connections	100%	90	100
4	Extent of Non-Revenue Water (NRW)	20%	15	20
5	Continuity of water supply	24 hours	5	24
6	Quality of water supplied	100%	100	100
7	Efficiency in redressal of customer complaints	80%	60	80
8	Cost recovery in water supply services	100%	90	100
9	Efficiency in collection of water supply related charges	90%	80	80
Sewage management (Sewerage and Sanitation)				
1	Coverage of toilets	100%	0	0
2	Coverage of sewage network services	100%	0	0
3	Collection efficiency of the sewage network	100%	0	0
4	Adequacy of sewage treatment capacity	100%	0	0
5	Quality of sewage treatment	100%	0	0
6	Extent of reuse and recycling of sewage	20%	0	0
7	Efficiency in redressal of customer complaints	80%	0	0
8	Extent of cost recovery in sewage management	100%	0	0
9	Efficiency in collection of sewerage charges	90%	0	0
Solid Waste Management				
1	Household level coverage of Solid Waste Management services	100%	70	90
2	Efficiency of collection of municipal solid waste	100%	70	90
3	Extent of segregation of municipal solid waste	100%	80	90
4	Extent of municipal solid waste recovered	80%	70	80
5	Extent of scientific disposal of municipal solid waste	100%	25	45
6	Efficiency in redressal of customer complaints	80%	60	70
7	Extent of cost recovery in SWM services	100%	60	90
8	Efficiency in collection of SWM charges	90%	60	100
Storm Water Drainage				
1	Coverage of Storm water drainage network	100%	90	100
2	Incidence of water logging / flooding	0%	0	0
SLB Status of 2018-19				
1	Coverage of Water Supply (24 X 7) in all Public/Community Toilets	24X7	yes	
2	Percentage of waste being processed scientifically*	100%	25	


 सहायक लेखाकार
 नगर पालिका परिषद
 पोखरी-गढ़वाल


 अभिशासी अधिकारी
 नगर पालिका परिषद
 पोखरी-गढ़वाल