

**GOVERNMENT OF INDIA
CENTRAL PUBLIC WORKS DEPARTMENT
OFFICE OF THE ASSISTANT ENGINEER
EE, HYD-I/2, CRPF CAMPUS, HYDERABAD.**

No.23(78)/2023/HYD-1/2/137

Dated:- 03/04/2023

To,
The Principal,
Kendriya Vidyalaya,
Barkas, Chandrayangutta,
Hyderabad.

Sub: Request to depute an Engineer to inspect School Building for issuing Building Safety Certificate-Reg.

Sir,

With reference to the above subject, please find enclosed here with the Structural Stability Certificate for the building of Kendriya Vidyalaya, CRPF, Barkas, Hyderabad. The school building has been inspected by the undersigned on 01.04.2023 along with Shri. Neeraj Verma, JE.

Yours Faithfully,

K.V. Singh
3/4/2023

**Assistant Engineer
O/o EE-HYD-I/2, CPWD,
Hyderabad**

Copy to:

1. The Executive Engineer, HYD-I, CPWD, HYD for favour of information.

sd

Assistant Engineer

ASSISTANT ENGINEER,
Hyderabad Central Sub-Div. 1/2
Central P.W.D., C.R.P.F. Campus,
Chandrayangutta Hyderabad 500026

STRUCTURAL STABILITY CERTIFICATE

On the basis of the physical inspection of the building by the undersigned on 01.04.2023 along with Shri. Neeraj Verma, JE as desired by Principal, KV, CRPF, it is certified that the Kendriya Vidyalaya, CRPF, Barkas, Hyderabad premises is safe and stable and fit for occupation. From the school authorities it is learnt that the school building was constructed by CPWD in the year 2002. The building is a RCC framed structure with G+2 floors.

Visual inspection shows that the condition of the building is satisfactory. No structural cracks were seen anywhere in the building. No Major distress or loss of structural integrity was observed.

K.V. Anjanna
3/4/2023
Assistant Engineer
O/o EE-HYD-I/2, CPWD,
Hyderabad

ASSISTANT ENGINEER,
Hyderabad Central Sub-Divn. I/2
Central P.W.D., C.R.P.F. Campus,
Shamdravandula, Hyderabad-500 084