




संख्या : 99/DB/EE-Silchar/2020-21/46

दिनांक: सिलचर; 20/05/2020

### STRUCTURAL SAFETY CERTIFICATE

It is certified that the building Kendriya Vidyalaya, Staff Quarters and Boundary Wall at NIT Silchar, Assam was constructed by CPWD and it is structurally safe for the year 2020-21.

However, the external paint of the building has started deteriorating and needs painting and routine repair works to safeguard the plaster and structural members of the building and boundary wall surrounding staff quarters needs patch plaster repair works and painting to safeguard against future deteriorating.

  
20/5/20  
EE-Silchar,  
CPWD, Silchar

Copy:

1. The Deputy commissioner, KVS, Regional Office, Tarapur, Silchar for information please.
2. The Principal, KV, NIT, Silchar for information please.

  
20/5/20  
EE-Silchar,