

**GOVERNMENT OF TELANGANA STATE  
ROADS & BUILDINGS DEPARTMENT**

From:  
**Sri P.Khajan Goud, B.E**  
Executive Engineer,  
(R&B) Division Office  
Miryalaguda

To:  
The Principal  
PM Shri Kendriya Vidyalaya School  
Near Kothuru Village  
Dilawarpur Road  
Miryalaguda Mandal  
Nalgonda District

**Lr. No. DB/ATO/ 2024-25/** **Dt. 24 - 08 - 2024.**  
Sir,

**Sub:-** Structural Soundness Certificate of **PM Shri Kendriya Vidyalaya School**, Building Situated at Near Kothuru Village Dilawarpur Road Miryalaguda Town & Mandal in Nalgonda District- issue of structural soundness certificate-Reg.

**Ref:- 1) Your** Letter-F.1-09/KV-MLG/2024-25, Dated:- 23-07-2024  
2) DEE/R&B/SD/Miryalaguda Lr.No. 18/2024-2025  
Dt:20/08/2024


\* \* \*

With reference to the letter 1<sup>st</sup> cited, I enclose here with the structural soundness certificate of **PM Shri Kendriya Vidyalaya School, Building**, Situated at Near Kothuru Village Dilawarpur Road Miryalaguda Town & Mandal in Nalgonda District, duly counter signed as requested by you for further necessary action.

**Encl:-**  
Certificate – 1 No.


Yours faithfully,

  
**Executive Engineer,**  
**(R&B) Division Miryalaguda**

  
24/8/24

## STRUCTURAL SOUNDNESS CERTIFICATE

I hereby certificate that, I have inspected the **KENDRIYA VIDYALAYA** School Building at Miryalaguda Town & Mandal in Nalgonda dist. today i.e. 20.08.2024 and the KENDRIYA VIDYALAYA School Building is found to be structurally sound and fit as on date.

  
20/08/24

Deputy Executive Engineer  
(R&B) Sub Division Miryalaguda

"counter signed"

  
24/08/24

Executive Engineer  
(R&B) Division, Miryalaguda  
Dist: Nalgonda.