

# FITNESS CERTIFICATE

(To be filled by the Asst. Engineer)

1. Name of the Officer - ANOOP T.P
2. Name of the School - KENDRIYA VIDYALAYA KADUTHURUTHY
3. Location with name of Edn. Dist./ Sub Dist. - VELLOOR, KADUTHURUTHY Edn. DISTRICT
4. Classification of buildings as specified in column 4 of the application for fitness certificate, and size
5. Period for which certificate is issued - 2025-26
6. Nature of defects if any
  - a) Foundation and basement
  - b) Superstructure
  - c) Doors and windows
  - d) Wood work wrought and put up
  - e) Roof
  - f) Flooring
  - g) Miscellaneous (cracks etc)
7. Any major defects noticed which will render the building unsafe in any manner Nil
8. Whether maintenance works have been done properly yes
9. Whether the structure is sound or not for conducting classes Structure is sound.

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure to flood etc.

2. Any addition observations if deemed necessary for the certificate may be furnished separately with the certificate.

Certified that school building was inspected by me on 24/10/2025

and found / fit / unfit to conduct classes for the period of / academic year

2025-26

for the reasons cited above.

To be Submitted to Assistant Executive Engineer Building Sub division, Palakkad

Place: Vaikom

Signature

Date: 24/10/2025

Designation

അനൂപ് ടി.പി  
അസിസ്റ്റന്റ് എക്സിക്യൂട്ടീവ്  
പൊതുജനസൗകര്യ വകുപ്പ് കെ.എ. വി.ഡി.വി.  
പാലക്കാട്