



भारत सरकार / GOVERNMENT OF INDIA

केन्द्रीय लोक निर्माण विभाग / CENTRAL PUBLIC WORKS DEPARTMENT



कार्यपालक अभियंता (अहमदाबाद) का कार्यालय / O/o THE EXECUTIVE ENGINEER (AHMEDABAD)

तीसरा तल, केन्द्रीय निर्माण सदन, सेक्टर-10-A, च-3 सर्कल के पास, गांधीनगर - 382010

3rd floor, Kendriya Nirman Sadan, Sector-10-A, Near CH-3 Circle, Gandhinagar-382010.

☎ 079 - 29660757 📠 079 - 29644033 ✉: eeacd.cpwd@gov.in, eeacdcpwd@gmail.com,

सं. 54(259)/का.अ./अहमदाबाद/हिन्दी/2024/557

दिनांक : 03/05/2024

सेवामें,

प्राचार्य,

केन्द्रीय विद्यालय नं.1, एम.आर. केम्पस,

शाहीबाग, पुलिस आयुक्त कार्यालय के पास,

शाहिबाग, अहमदाबाद - 380 004.

Email ID : kvno1shahibaugfs@yahoo.co.in

विषय : Safety Certificate of Main building & Primary building.

संदर्भ : आपके कार्यालय का पत्र संख्या 12029/Buil Cor/2024-25/KV SBAG ABD/AMN/90

दिनांक 02/05/2024.

महोदय,

Vide your above referred letter safety certificate was sought from this office, in this connection, this is to intimate that CPWD is not carrying out day to day maintainence & repair of the school infrastructure & hence CPWD can not issue such certificate. However following is intimated for your necessary action.

1) Main Building :

It is learnt that the age of main building is approximate 37 years. Renovation work has been done in 2021-22 in the building by CPWD & during the work it was observed that some structural members have developed cracks, columns of the shafts had vertical cracks. During the dismantling of roof waterproofing, it was observed that the slab concrete cover was peeling off. Such cracks wherever found were suitably repaired within the limited provision of the scope of work.

Keeping in view of the age of the building, it is recommended that structural audit from a Government engineering college or Institute of repute may be carried out by you, to assess the structural safety of the building.

2) Primary Building :

It is a very old heritage building with masonry load bearing structure. As per the visual inspection the building doesn't show distress or sagging.

However keeping in mind the age of the building, structural audit for this building is also recommended.

(सारांश कटारिया)

कार्यपालक अभियंता (अहमदाबाद),

के.लो.नि.वि., गांधीनगर

प्रतिलिपि :

1) उपायुक्त, केन्द्रीय विद्यालय संगठन, क्षेत्रीय कार्यालय अहमदाबाद, सेक्टर-30, गांधीनगर |

Email ID : kvsroadmn@gmail.com

2) सहायक अभियंता-II, के.लो.नि.वि, अहमदाबाद ।

कार्यपालक अभियंता (अहमदाबाद)