




**BANGALORE UNIVERSITY**  
**DEPARTMENT OF CIVIL ENGINEERING - U.V.C.E**

☎ : 080-22961155  
080-22961148  
☎ : +91-9448661664  
+91-9449173340

Jnana Bharathi, Bengaluru - 560 056.

To

**THE PRINCIPAL**  
AFS, Kendriya Vidyalaya No.1  
Jalahalli West  
Bengaluru - 560 015



Date: 08-05-2021

Sir,

**Sub:** Submission of Structural Stability Report of Kendriya Vidyalaya No.1, Jalahalli West Bengaluru - 560 015.

**Ref:** Letter No. F No.13-112(BU)KV-I JAL/2020-21/543, dated 12<sup>th</sup> March 2021 and Letter No. F No.13-112/KV-1 JAL/2019-20/791, dated 29<sup>th</sup> February 2020

With reference to the above, the detailed non-destructive tests are conducted and analysed for the stability of existing building belongs to Kendriya Vidyalaya No.1, AFS School Buildings at Jalahalli West, Bengaluru - 560 015.

As available data collected from the school authorities, the school campus consists of Annex building (1980), Primary Block (1978), Staff Quarters (1980), Main Secondary Building (1983), Computer Lab Building (2010).

Hence based on the non destructive test results and physical observations, the non destructive test results and remedial measures for damaged portions in detail is mentioned in the Detailed Report with photos.

In this all School Buildings and Quarters Buildings general safety, light, air and ventilation seem to adequate and the all School Buildings and School Building is capable of carrying the live load as per relevant IS Code and National Building Code (Part 6, Section 4, SP:7-2016).

Thanking you.

Yours faithfully.

Encl: Detailed Report - 2 copies

Kendriya Vidyalaya No.1  
Jalahalli West, Bangalore -15.  
ward No: 15. Date: 17/05/21

**Dr. KIRAN.T**  
B.E (Civil), M.E (Structures), Ph.D.  
Associate Professor,  
Department Of Civil Engineering,  
UVCE, Bangalore University,  
Bengaluru - 560056