



Oil and Natural Gas Corporation Limited

Fire Services: Mehsana Asset

No. MHN/FIRE/KV/2023-24

Date: 28.12.2023

Fire Safety Arrangement at KV ONGC, Mehsana


This is to certified that the premises of Kendriya Vidyalaya, ONGC Mehsana has been checked for possible Fire Hazards and risk and it is observed that except some combustibile materials, no significant Fire Hazard is available in premises.

Presently the existing fire Safety arrangement at Kendriya Vidyalaya, ONGC Mehsana is adequate with sufficient number of portable fire extinguishers (DCP ABC Type 6/9 kg -13 Nos, CO2type 4.5 kg- 07 Nos) / Fire Buckets (10 Nos.). These are checked and serviced in every quarter regularly by ONGC Fire Services, Mehsana.

The Fire Fighting training/drills are also conducted time to time by Fire Services of ONGC, Mehsana for educating the students and Teaching staff about Fire Prevention, Fire protection measures and safe evacuation of premises in the event of any Fire incident. The action to be taken in case of any Fire is also made aware for prompt and appropriate action to School staff.

In case of any fire incident, ONGC Fire Services are committed to response immediately for effective Fire Fighting.

With regards


28/12/2023

M A Sheikh

GM-I/C (Fire Services)
ONGC, Mehsana Asset