

BUILDING SAFETY CERTIFICATE

The School building of Kendriya Vidyalaya Ghumarwin Tehsil Ghumarwin Distt. Bilaspur (HP) and constructed by Two Rooms of Gram Panchayat Ghumarwin has been inspected by the junior Engineer Section on Dated 18/11/2025 As reported by Assistant Engineer Ghumarwin Sub Division vide letter No. PW-GSD-Building/2025 dt. 18/11/2025 It has been observed that no earthquake resistant provision have been adopted for this building and no structural drawing approved by the competent Govt. certificate Engineer have been produced at the time of inspection. Moreover, no assistance was taken from PWD for constructing the building. This structure is non-engineered structure. Hence, the structural safety of this building cannot be ensured. This department will not be held responsible for any type of loss of life and property etc. if this structure fails under any circumstances.

However, as per visual inspection the building has been found safe at present only. No officer/official of this department will attend plea in any Hon'ble court of law in case of any dispute. This certificate is valid for (1) year 2025 i.e. to 2026 as per notification received from the Addl. Chief Secretary (PW) to the Government of Himachal Pradesh vide letter No. PBW(B)E(3)95/2019 dated 05.05.2021.

Dated:-

Junior Engineer
Ghumarwin section-1
HP. PWD Ghumarwin

Assistant Engineer
Ghumarwin Sub-Division
HP. PWD Ghumarwin

CS

Executive Engineer
Ghumarwin Divison
HP. PWD Ghumarwin

रिंकु कुमारी/Rinku Kumari
प्राचार्या/Principal
केन्द्रीय विद्यालय घुमारवीं
Kendriya Vidyalaya Ghumarwin