

**By Regd Post/E-mail**  
Email:- kvbetul@yahoo.co.in

भारत सरकार  
सहायक अभियन्ता -II,  
कार्यालय कार्यपालक अभियन्ता -II,  
केलोनवि  
203, निर्माण सदन, 52-ए, अरेरा हिल्स,  
भोपाल - 462011



Government of India  
Assistant Engineer-II,  
O/o Executive Engineer-II,  
CPWD,  
203, Nirman Sadan, 52-A Arera Hills,  
Bhopal - 462011

दूरभाष - 0755-2677945, ई-मेल:- eebcd2cpwdbho-mp@gov.in

पत्रांक : 23(KV Betul)/AE-II /Bhopal/2024/ 230

दिनांक : 07/09/2024

To,

Shri R. N. Pandey,  
Principal,  
PM Shri Kendriya Vidhyalaya,  
Ganj Betul (M.P.)- 460001

Sub. : Certificate regarding structural safety of PM Shri Kendriya Vidhyalaya, Ganj, Betul (M.P.)

Ref. :- Your trailing email, Dated 08.07.2024.

R/Sir,

Vide above referred email, you have asked for structural safety certificate of above subjected school building.

Building of PM Shri Kendriya Vidhyalaya, Ganj, Betul (M.P.) was inspected by undersigned on dated 06.09.2024 and it is found structurally safe.

  
Assistant Engineer-II  
O/o EE-II, CPWD, Bhopal

Copy to:-

1. The Executive Engineer-II, CPWD, Bhopal for information please.

  
Assistant Engineer-II