

GOVERNMENT OF ANDHRA PRADESH  
ROADS AND BUILDINGS DEPARTMENT

From:  
N. Krishna Naik,  
Executive Engineer,  
(R&B) Division,  
Vijayawada

To  
The Principal  
PM SHRI Kendriya Vidyalaya No.1,  
Vijayawada

Letter No. Soundness Certificate/JTO2I/VJA/2024 Date:03.04.2025

Sir,

Sub:- (R&B) Division, Vijayawada – Structural Soundness Certificate for  
PM SHRI Kendriya Vidyalaya No.1, Vijayawada – Certificate issued –  
Reg.

Ref:- Representation of the Principal PM SHRI KV No.1, Vijayawada

\*\*\*


I enclose here with a Structural Soundness Certificate to the PM SHRI Kendriya  
Vidyalaya No.1, Vijayawada. This certificate is valid for the period 1 year i.e., from  
25.03.2025 to 24.03.2026.

Encl : Soundness Certificates.

Yours faithfully

  
Executive Engineer

(R&B) Division, Vijayawada

  
3/4/25



SOUNDNESS CERTIFICATE		
1	Address of the School/ College	: PM Shri Kendriya Vidyalaya No.1 Railway Colony, SN Puram, Vijayawada-11, Andhra Pradesh.
2	College/ School Running in	: RCC Building
3	No. of Floors	: G+2
4	Silt Floor/ground floor used as	: Class Rooms
5	constructed in the year	: 2002
6	constructed As per approved plan	: Yes, Plan enclosed
7	Present period up to which certificate is in force	: NA
8	Any cracks developed in the walls in superstructure and basement.	: No
9	Condition of lintels and walls above the lintel.	: Nil
10	Condition of beams and the Trusses	: Good
11	Development of Cracks	: Nil
12	Exposed reinforcement if any	: Nil
13	Condition of Doors and Windows	: Satisfactory
14	The width of the staircase flight is	: 1.48 m against required min width of 1.50m
15	Tread width is	: 0.29 m against required width of 0.30m
16	The height of rise	: 0.14m against required height of 0.15m
17	The height of railing	: 0.87 m against required minimum of 1.20m
18	The height of Corridor parapet wall	: 0.83 m
19	Doorway dimensions	: Width is 1.07 m against required minimum of 1.00m & 2.09m height against 2.00m
20	Height of Parapet wall	: 0.87 m
21	Internal corridor width	: 2.02m against 2.50m
22	Any Cantilever corridors	: 1.83 m
23	Number of exits	: 3 No
24	There is high tension electricity lines passing near to the building	: No
25	There is Petrol/Gas stations near to the building	: No
26	Grills are provided for all sides of balconies as children safety point of view	: Yes, provided
27	Building plan submitted	: Yes, Plan enclosed
28	Building Foundation and Structural design submitted	: No
29	Building was last painted in the year	: 2020
<p>The management is advised to attend the short falls identified in the above items and submit the details in this office, Otherwise soundnessCertificate will not be renewed by the department.</p> <p>How ever for the building is fit to run educational institution and this certificate is valid for a period of One Year i.e., from 25.03.2025 to 24.03.2026.</p>		

*[Signature]*  
Assistant Executive Engineer, (R&B)  
Buildings, Section-V, Vijayawada.

*[Signature]*  
Deputy Executive Engineer, (R&B)  
Buildings Sub Division, Vijayawada.

*[Signature]*  
Executive Engineer (R&B)  
Vijayawada.