

APPENDIX - VIII**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE.**No. 1(20)/AE/DWS/JRN/2018-19/499-500Date : 13/09/2018

It is certified that an inspection team headed by smf. Zalita
Debyanna, Jr. R/A (Name of Officers
 with designation) from DWS Sub - Division Jirania (Name of
 Department/Office) inspected the Kendriya vidyalaya, NIT
Complex, Jirania, Tripura (West) (Name & Address of
 the School) on _____ and found that the Kendriya vidyalaya,
NIT complex, Jirania, Tripura (W) (Name of school) has safe
 drinking water facilities for the students and members of staff of the institution and is maintaining
 the hygienic sanitation condition in the school building & the campus as per the norms
 prescribed by the Central/State/U.T Govt.

The above valid for a period of —.

Signature with Seal : [Signature]
 Name : _____
 Designation : Assistant Engineer
DWS, Sub-Division,
Jirania, Tripura (W).

To

Kendriya Vidyalaya
NIT Agartala, Jirania
Tripura (West) PIN 793046

(Name & Address of the Institution)