

**GOVERNMENT OF ANDHRA PRADESH
ROADS AND BUILDINGS DEPARTMENT**

From:
Sri A.D.D.Samarpana Rau, B.Tech.,
Executive Engineer,
(R&B) Division,
Guntur.

To:
The Principal,
Kendriya Vidyalaya,
Nallapadu Guntur.

Letter No. Soundness Certificate / A8 / GNT / 2024, Dated : 10.09.2024

Sub :- (R&B) Division, Guntur – Structural Soundness Certificates – “Kendriya Vidyalaya Nallapadu, Guntur- Issue-Regarding

Ref :- 1) Representation received by Kendriya Vidyalaya, Nallapadu Guntur Dated:-25.07.2024
2) Letter No. Soundness Certificates /SA/2024 Dated :- 09.09.2024 of the Deputy Executive Engineer (R&B) Special Sub-Division, Guntur.

* * * * *

With reference to the above, the Deputy Executive Engineer (R&B) Special Sub-Division, Guntur has personally inspected the **Kendriya Vidyalaya** on 03.09.2024 which was located in Nallapadu, Guntur . The existing building for the Primary School is RCC framed Structures G+2 Constructed in the year 1990 and building for Secondary school (G+2) and administration blocks (G+2) are constructed in the year 2014.

It is observed that the doors, windows and toilets are in good condition. Further grills are provided at the openings of the balcony and terrace. On visual observation, it is observed that the above building is **Structurally sound as on 04.09.2024 to 03.09.2025**

Encl:- Soundness Certificate.


Yours faithfully,

Hesperon 10/9/24
Executive Engineer
(R&B) Division, Guntur


Copy to the Deputy Executive Engineer (R&B) Spl Sub-Division, Guntur for information.


SOUNDNESS CERTIFICATE


This is to certify that I have inspected Kendriya Vidyalayam which was located in Nallapadu, Guntur on 03.09.2024 and on visual inspection it is observed that the existing building for primary school is RCC framed structures (G+2) constructed in the year 1990 and buildings for Secondary school (G+2) and administration blocks (G+2) are constructed in the year 2014 are structurally sound for running the Kendriya Vidyalayam from 04.09.2024 to 03.09.2025 i.e., one year.


Asst. Executive Engineer
(R&B) Section, Guntur

"*comple sidam*"


Executive Engineer
(R&B) Division, Guntur


10/9/24


9.9.24
Deputy Executive Engineer
(R&B) Spl Sub Division, Guntur

BUILDING SAFETY CERTIFICATE

Dated: 03.09.2024

No.

Certified that the existing building PM SHRI Kendriya Vidyalaya (name of the building or premises) at Nallapadu, Guntur (address) comprised of Ground floor basement(s) and 1st & 2nd floor (upper floors) owned/occupied by PM SHRI Kendriya Vidyalaya (name of the Institution)

requirements in accordance with National Building code Rules, and verified by the officers concerned of R&B department (Name of Department/ Govt.) on 03.09.2024 (date of inspection) in the presence of Principal, Kendriya Vidyalaya (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy upto classes XII (X/ XII) with effect from 04.09.2024 for a period of One year years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
2.
3.
4.

Issued on 09.09.2024 at Guntur by

* Strike out whichever is not applicable.

B. Jagadh Chd
9/9/24
Assistant Executive Engineer
(R&B) Section, GUNTUR.

Handwritten signature and date 9.9.24

Signature with Seal: EXECUTIVE ENGINEER
Name: (R&B) DIVISION, GUNTUR
Designation:

Name & Address of Department/ Office:

(Assistant Engineer & above officer of concerned Govt. Department only)

Note: This certificate should be signed / issued by Assistant Engineer & above officer of concerned Govt. Department only

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.