



Soundness Certificate

This is to certify that I have inspected the Kendriya Vidyalaya Tenali School situated at Sy. No: 90, 91, 109 & 110, Chinaravur Village, Tenali Mandal, Guntur District, Andhra Pradesh and during the inspection I found that the RCC roof ground and first floor building of the school are structurally sound. This certificate is valid for one year only.

Note: In some places, wall cracks have been identified in the ground and first floor parts and need to be repaired, and the wall cracks have been identified in the west side toilets part also and the painting has also faded, these need to be repaired.


06/10/25
Assistant Engineer (I/c)
(R&B) Section, Tenali


16/10/25
Deputy Executive Engineer
(R&B) Sub-Division, Tenali.