



Speed post



भारत सरकार  
केन्द्रीय लोक निर्माण विभाग  
कार्यपालक अभियंता, बीकानेर, सागर रोड, बीकानेर-334003  
फोन व फ़ैक्स : 0151-2230618

दिनांक 21/8/2020

पत्रांक: 19(85) / EE/Bikaner/2020/1188

सेवा में,

प्राचार्य,  
केन्द्रीय विद्यालय,  
भालेरी रोड,  
चुरु राजस्थान 331001

विषय: विद्यालय भवन का सुरक्षा प्रमाण-पत्र जारी करने बाबत।

संदर्भ: आपका पत्रांक फा.13 / के.वी.चुरु / 2020-21 / 1289 दिनांक 25.07.2020

उपरोक्त विषय एवं सदभित पत्र के क्रम में लेख है कि उक्त भवन का सुरक्षा प्रमाण-पत्र संलग्न कर आवश्यक कार्यवाही हेतु प्रेषित है।

संलग्न: उपरोक्तानुसार।

(मरत लाल मीना)  
कार्यपालक अभियंता  
केलोनिवि, बीकानेर

प्रतिलिपि: सहायक अभियंता- I, केलोनिवि, बीकानेर को सूचनाार्थ।

कार्यपालक अभियंता

## TECHNICAL CORRECTION/SAFETY CERTIFICATE

It is certified that School Building of Kendriya Vidyalaya Churu constructed by CPWD has been inspected by CPWD officials. It is certified that the School Building is safe and fit for use. But some place in school required repair.

कनिष्ठ अभियन्ता  
कैलोनिवि बीकानेर

श्री  
सहायक अभियन्ता(सि.)-1  
कैलोनिवि बीकानेर

कार्यपालक अभियन्ता(सि.)  
कैलोनिवि बीकानेर