

INS HAMLA SICKBAY  
MALAD (W), MUMBAI - 95  
13 Nov 21 at 6600hrs

SICKBAY, INS HAMLA

The vessel and exact nature of the  
contamination required

Bacterial logins  
of water

13 Nov 21 at 6600hrs

Date and hour of sampling

Nature and location of source of water  
the site of sampling

KV School

Nature and distance of any source from  
which on inflow of collection appears  
probable

BMC

Geological strata likely to effect the water  
constituents

If stored surface water, nature of  
collection surface and conditions stores

7. Bacteriological conditions - Heavy  
rainfall or drought

8. Any treatment the water has received

9. (a) Clarification

Clear

(b) Chlorination

Yes

(c) Softening

(d) Boiling



Pa-7501

प्रार्थी/PRINCIPAL

के.वि.भा.नौ.पो.हमला/KV INS HAMLA

मालाड (व.) / MALAD (W)

मुंबई ९५ / MUMBAI - 95

अवकाश

विद्यार्थी प्रबंधन समिति

केन्द्रीय विद्यालय, आय एम. एस. हमला

मालाड, मुंबई - ४०० ०९५

विद्यार्थी मोहाराणा  
(Eismila Moharana)  
म.स. कर्णार  
S. R. Moharana  
प्रधान उपनिर्देशक