

STRUCTURAL STABILITY CERTIFICATE

The building occupied by the school Kendriya Vidyalaya-2, Golconda , Hyderabad was tested using Non destructive testing method and is found to be safe and stable for the present loading condition . If the building is repaired and maintained as per the advice given in this report, the building is fit for occupation for the next 5 years . However there should be no change in the usage of the building and periodic maintenance is to be carried out regularly. .


Chief Co-ordinator, ICS.

