


6

FIRE SAFETY CERTIFICATE

KENDRIYA VIDYALAY AIRFORCE STATION, BIHTA

REPORT ON INSPECTION OF KV SCHOOL, AFS, BIHTA

KV AFS, Bihta School building was visually inspected and as per inspection it was found that there are 07 exit points in the building and sufficient number of fire extinguisher are available in the Vidyalaya. The building is safe for any kind of fire accident.




(P. Ghosh)

Wing Commander

Chief Administrative Officer, AFS, Bihta

15 Feb. 2022



प्रधान / PRINCIPAL
पीएम श्री केंद्रीय विद्यालय ए.एफ.एस. बिहटा
PM SHRI KENDRIYA VIDYALAY AIRFORCE STATION, BIHTA

Website: <https://afsbihata.kvs.ac.in>

(स्थापित/Established: 1991)

Phone: 06115-250041

पीएम श्री केन्द्रीय विद्यालय एएफएस बिहटा
(शिक्षा मंत्रालय, भारत सरकार)

वायु सेना स्टेशन, बिहटा

पीओ: बिहटा, जिला: पटना (बिहार)

पिन: 801 103

CBSE School No. 69040



PM SHRI KENDRIYA VIDYALAYA AFS BIHTA

(Ministry of Education, Govt of India)

AIR FORCE STATION, BIHTA

PO: Bihta, Dist: PATNA (BIHAR)

Pin: 801103

UDISE No. 10280503609

F.1/KVB/CBSE/2025-26

DATE : 23/06/2025

Undertaking for Fire Safety certificate

Building Safety certificate is under process for the session 2025-26

(Shubhendu Priyadarshi)

Principal

प्राचार्य / PRINCIPAL
पीएम श्री केन्द्रीय विद्यालय एएफएस बिहटा
PM SHRI KENDRIYA VIDYALAYA AFS, BIHTA



Scanned with OKEN Scanner