

# Eastern Railway

No:-SSE/II/KV/22

Dated: 07/07/2022

Sr. DEN/IV/ASN  
E. Rly, Asansol Division

Through:-AEN/I/UDL

Sub:-Renewal of Building Safety Certificate in respect of Kendriya Vidyalaya, Andal.  
Ref: Sr.DME/Dsl/Andal Diesel Shed'letter no. ADL/KV/1/22, dt.16.06.22.

\*\*\*\*\*

The Kendriya Vidyalaya, Andal is inspected on 07/07/2022 by the undersigned along with Sectional IOW. The above Vidyalaya is single story building with spacious and separate Emergency Exit. The observations are following:-

- (i) Joint cracks are developed in-between Medical building & main building.
- (ii) Minor cracked at Laboratory room.
- (iii) Cracks in partition wall jointing top with beam in-between Music Room & Class- IV and minor dampness on wall.
- (iv) Cracks in partition wall jointing top with beam in-between W.E. Room & Art room.
- (v) Partly roof leakage at Class-I.
- (vi) North side wall of Principal room is developed cracks.

All above cracks are required to be repaired early.

"Over all the building is safe for next 05 (Five) years as per visual inspection except major earth quake or any other natural devastation."

Sr. Section Engineer/Works/II  
Eastern Railway, Andal  
Sr. Section Engineer (Works)-2  
Eastern Railway, Andal

Copy to:- (i) Sr. DME/Dsl: For Kind information please.

- ✓ (ii) Principal, Kendriya Vidyalaya : for kind information & requested to in case the building is affected by flood or if settlement of wall /foundation or sagging of roofs etc, immediate inspection to be arranged to check the stability and safety of the building.

Sr. Section Engineer/Works/II  
Eastern Railway, Andal  
Sr. Section Engineer (Works)-2  
Eastern Railway, Andal

S. Singh  
18/08/22  
Principal  
केन्द्रीय विद्यालय अण्डाल  
KENDRIYA VIDYALAYA ANDAL  
जिला-वर्दवान / Distt.-Burdwan  
(ANB) 713921