

Annexure- C

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE


No.: Rwf/Kr/2026-27/02

Dated: 09/09/26

It is certified that an inspection team headed by **HARIDAS POIRAN (HI)** from **MEDICAL DEPARTMENT, RWF** inspected the **Kendriya Vidyalaya RWF Yelahanka Bengaluru** on **22/07/2026** (date of inspection) and on the basis of Water Test Report (Attached) bearing no. **23/2026** dated **22/07/2026** of **RH, RWF (PHED Lab)** certified that the **Kendriya Vidyalaya RWF Yelahanka Bengaluru** has safe drinking water facilities for the students and members of staff of the institution. School also maintains the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central/State/U.T. Govt.

This certificate is valid till **For One Month.**


S. S. E. D. RWF

Signature with Seal: 

Name: **YESHWANTH. V**

Designation: **ASSISTANT ENGINEER**

Name & Address of the Office / Department: **ENGINEERING DEPT.**

Assistant Engineer

रेल पहिया कारखाना

Rail Wheel Factory

यलहंका, बेंगलूर - 560 064

Yelahanka, Bengaluru - 560 064

To Kendriya Vidyalaya/RWF

22/7/2026

Report of Bacteriological analysis

Sample sent by	Sample No.	Source of water	MPN Count	Plat Count	SSP	NSSP	NSSP & FC
Count most probable number of bacteria/100 ml	20/2026	BSSB	NIL	-	SSP		
Test: Different	21/2026	BSSB	NIL	✓	SSP		
Uniform Test	22/2026	BSSB	NIL	✓	SSP		
Count Plat Count ml of water	23/2026	BSSB	NIL	✓	SSP		
P. Satisfied for table purpose.	24/2026	BSSB	NIL	✓	SSP		
SP: Not satisfied for table purpose	25/2026	BSSB	NIL	✓	SSP		
SP & FC: Water is satisfactory for drinking purpose and found	26/2026	BSSB	NIL	✓	SSP		

All the three samples are found satisfactory for drinking.

General
24/7/26

18.08.2026

RAH PATHOLOGY FACILITY
(RAILWAY HOSPITAL)

Report of Bacteriological analysis

Sample send by	Sample No.	Source of water	MPN Count	Plat Count	SSP	NSSP	NSSP & FC
MPN Count: most probable number of Bacteria/100 ml	23/2026 ORH East wing	BWSSB RAVERI	NIC	-	SSP	-	-
DC Test: Different Coliform Test	24/2026 Admin Building Tea Room	- " -	NIC	-	SSP	-	-
Plat Count: Plat Count per ml of water	25/2026 Staff canteen RWP	- " -	NIC	-	SSP	-	-
SSP: Satisfied for portable purpose.							
NSSP: Not satisfied for portable purpose.							
NSSP & FC: Water is not satisfactory for drinking purpose and E.coli found.	26/2026 Canteen RA/RW	- " -	NIC	-	SSP	-	-

All the ~~three~~ three samples are found potable and satisfactory for drinking.

Original

29/8/26