



**OIL AND NATURAL GAS CORPORATION LTD
INFRASTRUCTURE MAINTENANCE GROUP
8th FLOOR, B.S NEGI BHAWAN, TEL BHAWAN
DEHRADUN – 248001**

Certificate of Safety for FY 2026-27

(Applicable for the Civil Related Items Only)

The building of Kendriya Vidyalaya, ONGC, Dehradun is a G+1 & G+2 storied RCC Structure along with boundary wall.

The Building/ boundary wall are properly maintained with respect to civil related works based on “Condition Assessment/Structural Audit” it is to certify that structure is adequately safe and fit for human habitation.

G. Sri Harsha
14/2026

Sri Harsha Gamidi
हर्षा गामिडी / Harsha Gamidi
अधीक्षण अभियन्ता (सिविल) / SE (Civil)
इन्फ्रास्ट्रक्चर समूह / Infrastructure Group
ओएनजीसी, देहरादून / ONGC, Dehradun