

CERTIFICATE

This is to certify that the main building of Kendriya Vidyalaya Sukna, located near Tarapore Vihar, has been inspected and found to comply with the fire safety standards. Therefore, the building is deemed safe for occupancy from a fire safety perspective.



COUNTERSIGNED

अध्यक्ष/ Chairman

केन्द्रीय विद्यालय/ Kendriya Vidyalaya
सुकना, प. ब./ Sukna, W.B.



(बुधन्शु कुमार सिंह)
(Budhanshu Kumar Singh)
ई ई/एम
AE E/M
एजीई ई/एम सुकना
AGE E/M Sukna