



CERTIFICATE

It is certified that Building Nos. Block A, Block B and Block C and staff quarters at verified visually and found no superficial structural defects in the Kendriya Vidyalaya No. 3, Jalandhar Cantt.

Station : Jalandhar Cantt.

Date : 21 NOV 20


GAURAV TRIPATHI
CAPT.
AGE B/R-I (WEST) JRC


PRINCIPAL
केंद्रीय विद्यालय संख्या-3,
KENDRIYA VIDYALAYA NO. 3
जालंधर छावनी
JALANDHAR CANTT