



TO WHOM SO EVER IT MAY CONCERN
BUILDING SAFTY CERTIFICATE

It is certified that the building and boundary wall of "Kendriya Vidyalaya Mandi" District Mandi (HP) as reported by the Assistant Engineer, Kamand Sub-Division, HPPWD Kamand seems to be safe to run school classes under normal condition for the year 2024-25 as per the visual inspection of the building. However, structural stability cannot be ascertained due to non-availability of structural design, drawings and IS specification required for the building construction. This certificate is being issued purely on the basis of visual inspection and issuance of this certificate does not confer any legal and financial liabilities on the issuer please.

Executive Engineer,
Mandi Division No.1,
HPPWD at Padhar.

No. PW/MDI-1/WA/Safety Certificate/2024 1414-15 dated: - 8/5/

Copy to the Assistant Engineer, Kamand Sub-Division, HPPWD Kamand with reference to his office letter No.PW.KSD/B-19/2023-24- 108 dated 18.04.2024.

Copy to the principal Kendriya Vidyalaya Mandi,
District Mandi (HP).

Executive Engineer,
Mandi Division No.1,
HPPWD at Padhar.

Handwritten signature and date 18/05/2024.