



भारत सरकार

केन्द्रीय लोक निर्माण विभाग

कार्यपालक अभियंता, निर्माण मंडल-4

के.लो.नि.वि., आई.ए.आर.आई. पूसा, नई दिल्ली-110012

दूरभाष: 25841056, ई-मेल: eeed4cpwd@gmail.com

प.स.- 11(KVS)/का. ई/नि.म.-4/2025-26/ 3567-18 दिनांक: 15-9-25

To,

The Principal
Kendriya Vidyalaya
Tagore Garden
New Delhi-110027
Email:- pmsheviktagoregarden@kvsrodelhi.in

विषय:- वर्ष 2025-26 हेतु संरचनात्मक सुरक्षा प्रमाण पत्र जारी करने के सम्बन्ध में।

Ref:- Your office letter no- 19046/Cons./Sec-08/Rohini/2nd/2024-25/90 dated 04.09.2025

Sir/Mam,

With reference to above mentioned subject, there is request for providing safety certificate of school buildings. In this regard, it is stated that Assistant Engineer-II/CD-IV, visited the site and found that "the life and structural safety of the buildings depends upon the regular maintenance of the building which is being carried out by the School authority themselves". Principal of school have to be more cautious about the maintenance for cleaning of roof, chajjas, repair of seepage, minor cracks and internal & external finishing etc regulary.

However "as per structural safety certificate, structural safety of the building concerned, structure is safe" as on date of visit.

कार्यपालक अभियंता
निर्माण मण्डल-4,
के०लो०नि०वि०, पूसा,
नई दिल्ली -110012.

Copy to:

1. Kendriya Vidyalaya Sangathan (Hqrs), 18, Institutional Area, SJS Marg, New Delhi-110016 for information.
2. Assistant Engineer-2, CPWD, Press Colony, Mayapuri, New Delhi for information.


कार्यपालक अभियंता