ISRO HQ. CEPO

No. CEPO/CPG/266/KVNAL

Dt: 25.03.2024

Sub: Safety Certificate for KV NAL – Committee Report. – Reg. Ref: Letter No. F.13044/KVNAL/2023-24/751 Dtd. 07.02.2024.

With reference to the letter cited above, it is to inform that a Technical Committee has inspected the Kendriya Vidyalaya Building & Staff quarters and found that the KV NAL Building & Staff quarters are in safe condition from structural & electrical point of view and fit for usage. The report of the committee is enclosed herewith for taking further necessary action at your end.


Encl: a/a

(H.S. Ravikumar)
Director, CEPO

To,
Principal,
KV NAL Campus,
Vimanapura,
Bengaluru – 560017

CC to:

Director, NAL: For kind information Group Director, C&MG, URSC.



GOVERNMENT OF INDIA DEPARTMENT OF SPACE CIVIL ENGINEERING PROGRAMME OFFICE ISRO HQ, BENGALURU

No. CEPO/KVNAL/386(B)

Date: 21.03.2024

Sub: Safety Certificate for Central School Building (KV NAL) Bengaluru - Reg.

Ref: 1) Committee constitution letter Dt. 21.02.2024.

2) Letter No. F.13044/K.V.(NAL)/2023-24/751 Dt. 07.02.2024

The Principal, KV NAL vide letter (2) under reference has requested for Safety Certificate for Central School Building & staff quarters. A committee was constituted vide letter cited at ref-1 for inspection of building and submission of a report.

The committee had inspected the KV NAL building on 21.03.2024 and following report is submitted.

The KV NAL school building & staff quarters has been inspected by the committee. It is found that the school building & staff quarters is found to be in safe condition from the structural and electrical safety point of view and is fit for usage.

Engineer-SF(Electrical) CEPO, Member Secretary

Engineer-SG, CMG-URSC

Member

(Manjunath P.)

Chief Scientist & Advisor (W&S)

NAL, Member

(S. Thandapani)

Engineer-SG Head Designs, CEPO

Chairman