

Building Safety Cert.



भारत सरकार
कार्यपालक अभियंता, निर्माण मंडल-4
के.लो.नि.वि., आई.ए.आर.आई. पूसा,
नई दिल्ली-110012

दूरभाष: 25841056
ई-मेल: eecd4cpwd@gmail.com

Govt of India
Executive Engineer, CD-4
CPWD, IARI Pusa,
New Delhi-110012

Telephone-25841056,
Email-eecd4cpwd@gmail.com



संख्या: 58(KVS)/का.अभि./ले.शा./नि.म.-4/2025-26/1159 दिनांक : 7.03.2026

सेवा में,

प्राचार्या

पी0एम0श्री केन्द्रीय विद्यालय,
सैक्टर-8, रोहिणी, दिल्ली-110085

Email-pmshrikv.sec8rohini@gmail.com

Sub:- Structural Safety Certificate of the School Building.

Ref: Your office letter No. F.19046/Cons./Sec-08/Rohini/2nd/2025-26/144 dated 03.03.2026. and
This office AE-II Letter No. 54(KVS)AE-II/CD-IV/2025-26/82 dated 05.03.2026

महोदय,

उपरोक्त संदर्भित पत्र के द्वारा मांगी गई विद्यालय की Structural Safety से संबंधित रिपोर्ट
आपको इस पत्र के साथ संलग्न कर आवश्यक कार्यवाही हेतु प्रेषित है।
संलग्न: उपरोक्त संदर्भित पत्र।

07/2/2026

कार्यपालक अभियंता
निर्माण मण्डल-4,
के0लो0नि0वि0, पूसा,
नई दिल्ली 110 012.

प्रतिलिपि:-

1. सहायक अभियंता-2, नि0मं0-4, के0लो0नि0वि0, मायापुरी नई दिल्ली को सूचनार्थ।

कार्यपालक अभियंता



भारत सरकार
केन्द्रीय लोक निर्माण विभाग
कार्यालय सहायक अभियन्ता (सिविल)
उपमंडल-II, निर्माण मंडल-IV
प्रेस कॉलोनि, मायापुरी, नई दिल्ली-110064
दूरभाष: 25841058, ई-मेल: ae5cpwd@yahoo.in

सं०-54(KVS)/स०अभि०-2/नि०मं०-4/2025-26/ 82.

दिनांक:- 05/03/2026

सेवा में,

कार्यपालक अभियन्ता
नि०मं०-4 के०लो०नि०वि०,
पूसा नई दिल्ली।

7494

6/3/26

05/3/26

विषय - Structural safety Certificate of the School Building.

संदर्भ - Letter No. F. No. 19046/Cons./Sec-08/Rohini/2nd/2025-26/144 dated 03.03.2026 of
Principal PM Shri Kendriya Vidyalaya Sec-08, Rohini, New Delhi.

महोदय,

With reference to above cited subject, it is intimated that the School building of PM SHRI Kendriya Vidhyalaya, Sector-08, Rohini, was inspected by the undersigned and through visual inspection the building seems to be structurally safe for a period of one year.

सहायक अभियन्ता -II
के०,लो०,नि०,वि,प्रेस कॉलोनि
मायापुरी, नई दिल्ली।