

SAFETY AND STABILITY CERTIFICATE FOR THE FY 2022-2023

1. It is certified that the Vidyalaya building, staff qtrs and compound wall of Kendriya Vidyalaya No 03 AF-II Jamnagar constructed by the MES, AF station in year 1994 are inspected by MES and declared structurally safe and stable as per visual inspection. It is also intimated that in school building especially, following defects have been observed:-


- (a) Minor cracks develops in architectural design of front view.
- (b) Chajja have minor cracks with concrete of fins & facia fallen down exposing swollen steel reinforcement on rear side.
- (c) Some vertical minor cracks are observed in certain columns on rear side.
- (d) In front 2 to 3 columns, concrete is broken and steels are exposed.

2. In view of the above it is advised that routine repair/maintenance may please be done to enhance the life of structure and keep the building in safe condition.

आवक (Inward):	696
फाइल सं. (File No.):	F. 120112
दिनांक (Date):	15-11-2022

Station : Jamnagar (IDSE)

Dated : 15 Nov 2022



(Nandan Kumar, IDSE)  
EE  
Garrison Engineer