



भारत-सरकार
GOVERNMENT OF INDIA
केंद्रीय नौक निर्माण विभाग
CENTRAL PUBLIC WORKS DEPARTMENT



o/o the Executive Engineer,
Bengaluru Central Division-2, CPWD, 12th floor, Near Domlur Flyover,
Sir Visweswraya Kendriya Bhawan Domlur, Bengaluru-560071

Tel 080-25356733

E-mail: bcd2cpwd1@gmail.com

क्र. 24(4)/बीसीडी-II/2019-20/ 933

आवक/आवक/19.2019

सेबामें,

~~The Principal,~~
Kendriya Vidhyalaya,
No.1, AFS, Jalahalli,
Bangalore 560 015.

से प्राप्त किया/Receive from

प्राप्त हुआ/Received on

फाइल सं./File No. CPWD

कलर्क/Clerk

विषय: - Safety Certificate of KV ASC Centre - reg.

संदर्भ :- 1. Your letter No.F.C.19/KV-ASC/2019-20/225 dated 01.08.2019
%%%%%%%%%

महोदय,

With reference to above, the undersigned has inspected your school on 20.08.2019 along with Sri. Sreekumaran K, Assistant Engineer, CPWD subsequently 26.08.2019 by Sri. Sreekumaran K, Assistant Engineer, CPWD along with Junior Engineer. The school building and compound wall were found to be safe from visual inspection. However detailed structural investigation is required to establish structural stability of the buildings.

Your's faithfully

(Jyoti Shankar Behera)
कार्यपालक अभियंता,
बें.कें.मंडल २, बेंगलुरु-७१

Office (U)

To keep in safety file for records

प्रतिलिपि:- 1) The Assist. Engineer, BCSD 2/II, CPWD, Bangalore for information.

कार्यपालक अभियंता,

16/12