

Office of the Executive Engineer, Constn. Divn. No.1,
PWD B&R Br. Ferozepur

Building Safety Certificate

- A) Sub. Division Engineer, Constn. Sub Divn. Pwd B&R Br. Jalalabad have visisted the School Building of Kendriya Vidyalaya, BSF, Jalalabad (W), District Fazilka on 17-06-2021 and have visually inspected it from all angles of safety and it fit for the school.
- B) In case any addition/alternation or expansion and modification to this building, is to be carried out under the supervision of a qualified Engineer and certificate should be obtained after completion.
- C) In case the building is affected by flood or if there is any settlement of walls, foundational sagging of roofs etc. immediate inspection be arranged to check safety of building.
- D) This building can safely be occupied for normal use for year 2021-22 (31.3.2022)
- E) This Certificate is not valid for any Legal Cases.

Executive Engineer,
Constn. Divn. No.1, PWD B&R Br
Ferozepur


Endst. No. spl-03-04

Dated: 29-06-2021

A copy of above is forwarded to the:

1. Principal, Kendriya Vidyalaya, BSF, jalalabad (W), District Fazilka. DA/ Certificate
2. Sub Divisional Engineer, Constn. Sub Divn. PWD B&R Br, Jalalabad in the references of their office Letter No.183 Dt. 21.06.2021

for information and necessary action.


Executive Engineer,
Constn. Divn. No.1, PWD B&R Br
Ferozepur