



STRUCTURAL SOUNDNESS CERTIFICATE

1. This is to certified that during visual observation carried out by the repersantative of this office, no cracks or settlement of walls/ ground has been noticed anywhere in the building of Kendriya Vidyalaya No.1 Binnaguri. The building is already is use can be further used for school purpose.
2. Drinking water to Kendriya Vidyalaya No.1 Binnaguri supplied by MES which is safe to drink.



(Rajesh Kumar, IDSE)
EE
Garrison Engineer (South)

**RAJESH KUMAR, IDSE
EE
GARRISON ENGINEER (S)
BINNAGURI**