

STRUCTURAL SOUNDNESS CERTIFICATE

This is to certified that during visual observation carried out by the repersantative of this office, no cracks or settlement of walls/ ground has been noticed anywhere in the building of Kendriya Vidyalaya No.1 Binnaguri. As per present scenario the bldg can be used for more 01 year. However any distress in between please to be intimated to under signed at earliest.




(Shailendra Soni, IDSE)
EE
Garrison Engineer (South)