



Water Testing Report Perform by SSE/W/WS/LMG with Medical Department

Date: 03.08.2024

Location	Residual Chlorine	Ph. Value	Turbidity	Iron Test	TDS	Bacteria
Acceptable limit	0.2ppm	6.5-8.5	5.0 NTU	0.3ppm	500	Test perform by Medical Department
At station(Surface Water)	0.90	7.00	2.75	0.03	300	
At Filter House(Surface Water)	0.80	7.50	3.50	0.02	350	
At Hospital(Surface Water)	0.30	7.50	3.00	0.3	400	
Deep tube Well						
At Hospital	0.20	7.00	2.00	0.02	350	
At Station	0.20	7.50	2.00	0.02	310	
At DTS Hill Colony	0.20	7.30	2.00	0.02	310	
At A/C Colony	0.20	7.50	2.50	0.06	350	
At Master colony	0.20	7.50	2.50	0.08	290	
At New Colony	0.20	7.00	2.00	0.05	300	
Front of Employees Union Office	0.20	7.20	2.00	0.10	350	
At RPSF Colony	0.20	7.50	1.00	0.05	340	


 Sr. Div. Medical Officer
 J. F. Div. Lunding
 वरिष्ठ मंडल स्वास्थ्य अधिकारी
 पु. सी. रेलवे, लामोहन


 9/8/24
 Health & Malaria Inspector/Grade
 J. F. Div. Lunding


 03/8
 Senior Section Engineer (Works)
 Water Supply, LMG, N. F. Rail