


भारत सरकार / Government of India

केन्द्रीय लोक निर्माण विभाग / Central Public Works Department









No.25(KV)/2021-22/EE/HYD-IV/857

Date: | / .08.2021

To The Principal, Kendriya Vidyalaya, Nalgonda, Beside YSR Park, Ram Nagar, Nalgonda-508 002.

Sub: Issue of Building Safety Certificate for School Building for Kendriya Vidyala at

Nalgonda for the year 2021-22.

Ref: F.No. /KVNLG/2021-22, Dated:19.07.2021

Sir,

With reference to the above subject and letter under reference, it is to state that the school building was constructed adhering to all the relevant IS Codes, CPWD specifications and quality control parameters and the building is "Structurally sound and safe for conducting the classes for year 2021-22.

For longevity of the building, the regular maintenance like cleaning of terraces, rain water pipes, painting etc is required to be done.

केन्द्रीय लोक निर्माण विभाग, हैदराबाद

1. The Assistant Engineer, NCSD, CPWD, Nizamabad for information and necessary action.

कार्यपालक अभियंता