



Office of the AGE B/R I
Military Engineer Service
Fort St George
Chennai – 09


202/Dep~~56~~/E2 dt 23 Jul 2025

The Principal
Kendriya Vidyalaya Island Grounds
Chennai – 600 002

STABILITY CERTIFICATE OF KENDRIYA VIDYALA
ISLAND GROUNDS SCHOOL BUILDING

1. It is certified that the School building and structure of Kendriya Vidyalaya Island Grounds Chennai is apparently safe at present by visual inspection under normal condition and fit for occupation of session 2025-26 i.e upto 31 May 2026.
2. However, it is recommended the periodical maintenance and timely repair and Spl repairs to make good of concrete, roof treatment, joinery, plastering, painting, electric fitting, electric fittings etc to enhance the life of building further.


(C S Rao)
AE (Civ)
AGE B/R I



(MV Rami Reddy, IDSE)
EE
Garrison Engineer