

BUILDING SAFETY CERTIFICATE

It is certified that the School Building , Staff Quarters and Boundary wall of PM SHRI Kendriya Vidyalaya, AFS Laitkor Peak, Shillong has been visually inspected by the undersigned from the structural and general safety point of view.

Based on the visual inspection carried out, some cracks in the wall and columns can be seen, however exactly depth of the cracks and their effects on the structural integrity can only be ascertained after conducting structural audit of the building.

The School Building , Staff Quarters and Boundary wall appears to be structurally safe and suitable for use under normal conditions.

However, this certificate is based on visual inspection only and does not constitute a detailed structural assessment of the building. In view of the age, usage and prevailing environmental conditions, it is advisable to carry out a detailed Structural Safety Audit/Structural Health Assessment by a competent structural engineer/authorized agency to establish the overall structural condition and long-term safety of the building.

This certificate is issued for official record and necessary use, subject to the above observations and recommendations.

Place: Shillong

Date: 27-08-2026




(AGE B&R)
MES, AFS Laitkor Peak, Shillong
Signature & Official Seal

(S Verma, IDSE)
AEE (Civ)
AGE B/R - II, AF, Shillong